

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:			
Company	Russell Hardy		
OGM	Karl Houskeeper Environmental Scientist III		

Inspection Report

Permit Number:	C0150015
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, June 10, 2008
Start Date/Time:	6/10/2008 7:00:00 AM
End Date/Time:	6/10/2008 9:30:00 AM
Last Inspection:	Tuesday, May 13, 2008

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: <u>Clear, Temp. 67 Deg. F.</u> InspectionID Report Number: <u>1672</u>

Accepted by: jhelfric

7/7/2008

Permitee: CONSOLIDATION COAL CO

Operator: CONSOLIDATION COAL CO SESSER OPERATIONS

Site: EMERY DEEP MINE

Address: PO BOX 566, SESSER IL 62884

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Mineral	Ownersh	ip
---------	---------	----

Types of Operations

5,568.00	Total Permitted
62.50	Total Disturbed
	Phase I
	Phase II
	Phase III

]	Federal	✓	Underground
]	State		Surface
]	County		Loadout
a			

✓ Fee☐ Other☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permit Conditions: Emery Deep has one permit condition. The permittee must submit water quality data in an electronic format through the Electronic Data Input web site.

Inspector's Signature:

Manus A Dusbeeger

Date

Tuesday, June 10, 2008

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150015 Inspection Type: PARTIAL

Inspection Date: Tuesday, June 10, 2008

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓			
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	✓			
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		✓	
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150015 Inspection Type: PARTIAL

Inspection Date: Tuesday, June 10, 2008

Page 3 of 3

2. Signs and Markers

The mine ID signs are in place and contain the required information.

4.d Hydrologic Balance: Water Monitoring

Fourth quarter 2007 water monitoring is in the EDI website and has been uploaded. First quarter 2008 water monitoring is done and needs to be submitted to the EDI website. Water monitoring is current.

7. Coal Mine Waste, Refuse Piles, Impoundments

Refuse pile appeared stable, no visible hazards.